



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795

**\*\*\*\*FOR COMPLIANCE WITH SERVICE BULLETIN SB-78\*\*\*\***

Per Service Bulletin SB-78, all Robinson Astro, Raven (S/N 0001 thru 2064), and R44 Raven II helicopters (S/N 10001 thru 12890) must complete the retrofit of KI-196 *R44 Series Bladder Fuel Tank* by no later than December 31<sup>st</sup>, 2014. To minimize aircraft downtime to comply with this SB, many operators are electing to coordinate installation of the Kit with the overhaul of their helicopter.

**NOTE:** Robinson has maintained current pricing for the kit through the end of 2012, though it may increase at any time without notice.

**NOTE:** Rotorcorp's experience is showing that the KI-196 lead time is SIGNIFICANTLY longer than that of an overhaul kit. There is currently a 45-60 day lead time for R44 Overhaul Kit. In order to avoid costly delays, Customer's planning to coordinate kit installation with overhaul should plan to order the KI-196 at least two full months (60 days) prior to overhaul kit order.

For details on SB-78 please visit [www.rotorcorp.com/publications/](http://www.rotorcorp.com/publications/)

Rotorcorp Bladder Kit Pricing:

KI-196-1 <i>R44 Main Aux. Bladder Kit</i> (S/N 0001 thru 2064).....	\$7700
KI-196-2 <i>R44 II Main Aux. Bladder Kit</i> (S/N 10001 thru 12890).....	\$7700